

To: Wagner, Christine[Wagner.Christine@epa.gov]
From: Nonresponsive based on revised scope
Sent: Mon 11/1/2021 7:36:31 PM (UTC)
Subject: RE: Shiloh Church Rd field work

Hi Chris,

Ex. 6 Personal Privacy (PP)

The cause of a jump like that could be attributed to a few things, like changing GW levels at the time of sampling, or the excavation activities could cause a temporary increase in concentrations

Collecting a sample in Jan 2022 would give us another piece of data that we can look at, which will give us an almost full seasonal (fall 2020, summer 2021, and winter 2022) data for the site.

Thanks,

From: Wagner, Christine <Wagner.Christine@epa.gov>
Sent: Friday, October 29, 2021 2:54 PM
To: Nonresponsive based on revised scope
Subject: RE: Shiloh Church Rd field work

Good Afternoon

Possibly. Have you looked at the residential data at all to try and figure out why Ex. 6 Personal Privacy (PP) was such an anomaly? Have you checked the CLP numbers and QA/QC package? I still have lots of questions regarding START work

Thanks
Chris

From: Nonresponsive based on revised scope
Sent: Friday, October 29, 2021 2:02 PM
To: Wagner, Christine <Wagner.Christine@epa.gov>
Subject: Shiloh Church Rd field work

Good afternoon Chris,

Just checking in on this project. Do you think we will be doing a field work before the planned Jan 2022 GW sampling?

Thanks,

Nonresponsive based on revised scope PMP | Senior Project Manager

Nonresponsive based on revised scope

This message, including any attachments, may include privileged, confidential and/or inside information. Any distribution or use of this communication by anyone other than the intended recipient is strictly prohibited and may be unlawful. If you are not the intended recipient, please notify the sender by replying to this message and then delete it from your system.